

Journeyman Upgrade Class Schedule 2008/2009

These classes and class dates are an attempt by the Local Union and the Apprenticeship Committee to offer skills upgrading to our membership. This is done to help keep our members highly skilled and more employable and to keep our employers more competitive.

All of these classes are offered to members of Ironworkers Local 584. If you sign up for these classes please be considerate and respectful by:

- calling to register for the class at least 1 week in advance
- planning to attend EVERY day – if classes span more than one day
- showing up on time – all classes start at 8:00 am sharp
- staying for the entire class – some are 10 hours or more in one day
- calling as early as possible if you are unable to attend a class you signed up for

The classes provided – **except the welding and the OSHA/Sub Part R** – are scheduled classes for the apprentices who are enrolled in the apprenticeship school. A full class schedule is available on the website. If you are interested in taking any class which does not appear on this list, simply contact the apprenticeship school for more information.

OSHA/Sub Part R – 2008

Friday November 7th, 8:00 am to 5:00 pm

Friday December 5th, 8:00 am to 5:00 pm

Foreman Training – 2009

March 30th thru April 1st, 8:00 am to 5:00 pm – this is a 3 day class

April 6th thru 8th, 8:00 am to 5:00 pm – this is a 3 day class

Layout Instruments – 2009

March 11th and 12th, 8:00 am to 5:00 pm – this is a 2 day class

Blueprint Reading – 2009

January 8th and 9th, 8:00 am to 5:00 pm – this is a 2 day class

January 22nd and 23rd, 8:00 am to 5:00 pm – this is a 2 day class

June 18th and 19th, 8:00 am to 5:00 pm – this is a 2 day class

OSHA/Sub Part R – 2009

Friday February 6th, 8:00 am to 5:00 pm

Friday March 6th, 8:00 am to 5:00 pm

Friday April 17th, 8:00 am to 5:00 pm

Friday May 8th, 8:00 am to 5:00 pm

Friday June 5th, 8:00 am to 5:00 pm

NOTE: You must call and sign up for the classes at least one week in advance to ensure enough materials are available for the number of students attending. If you do not sign up at least 1 week in advance and we are short on materials you will not be allowed to attend.

Journeyman Weld Testing

The apprenticeship school will have an instructor and welding inspector available for journeyman training and testing on the following dates:

Keep in mind these classes and tests require the hiring of an extra employee. If you do not call and sign up at least 1 week in advance, the class will be cancelled to save employment costs.

2008 Weld Training and Testing Dates	Class
November 3 rd	Weld theory and symbols/ Weld practice
November 4 th and 5 th	Weld practice and testing
December 1 st	Weld theory and symbols/ Weld practice
December 2 nd and 3 rd	Weld practice and testing
December 29 th	Weld theory and symbols/ Weld practice
December 30 th and 31 st	Weld practice and testing

2009 Weld Training and Testing Dates	Class
February 2 nd	Weld theory and symbols/ Weld practice
February 3 rd and 4 th	Weld practice and testing
March 2 nd	Weld theory and symbols/ Weld practice
March 3 rd and 4 th	Weld practice and testing
April 13 th	Weld theory and symbols/ Weld practice
April 14 th and 15 th	Weld practice and testing
May 4 th	Weld theory and symbols/ Weld practice
May 5 th and 6 th	Weld practice and testing
June 1 st	Weld theory and symbols/ Weld practice
June 2 nd and 3 rd	Weld practice and testing

NOTE: You must call and sign up for any welding class at least one week in advance. Classes will be canceled if there are not any Journeymen signed up at that time. **Every Journeyman must attend the Monday weld theory and symbols class or they will not be allowed to weld at all.**