

Journeyman Upgrade Class Schedule 2012

Article X – Safety Provisions of the new Collective Bargaining Agreement stipulates that all Journeymen must have the following Classes/Certifications:

- All Iron Workers must agree to abide by the Employers Sexual Harassment Policies.
- All Iron Workers must remain current on the Impact Drug Test.
- All Iron Workers must complete the OSHA Ten (10) hour and Sub Part R (Steel Erection) Safety courses at least every five (5) years.
- All Journeymen Iron Workers must have Rigging and Signaling cards.

The following classes have been set up to allow members to comply with the above contract language:

OSHA 10 hour including Sub Part R: (2 day class – you must attend both days)

Class start time is 8:00 am

January dates - 16th and 17th

March dates - 12th and 13th

April dates - 9th and 10th / 23rd and 24th

May dates – 21st and 22nd

OCIBSEA Rigging and Signaling: (1 day class)

Class start time is 8:00 am

January dates – 18th / 19th / 20th

March dates – 14th / 15th / 16th

April dates – 11th / 12th / 13th / 25th / 26th / 27th

May dates – 23rd / 24th / 25th

For those wishing to attend an OSHA 30 class, required to be a foreman or superintendent by some companies, we have the following set up:

OSHA 30 hour including Sub Part R: (4 day class – you must attend all 4 days)

Class start time is 8:00 am

The OSHA 30 hour classes will coincide with the new apprentice's classes and a schedule will be put out for them as they are established.

PLEASE CALL TO REGISTER FOR THE CLASS YOU WISH TO ATTEND. WE NEED TO KNOW IN ADVANCE HOW MANY COPIES OF THE MATERIALS WE WILL NEED.

PHONE NUMBERS:

BRIAN TANNEHILL 918-234-4980

MICHAEL RICHARDS 918-437-1446